



RTR Services Inc. DOZER CONDITION REPORT

RTR #: 6124186-02 ACCOUNT NUMBER: ACCOUNT NAME:

YEAR: 2004 VIN/SN: CAT0525BV3KZ01678 MAKE: CAT MODEL: 525B COLOR: EXTERIOR: Yellow INTERIOR: ENGINE: CAT Diesel KEYS: IGNITION: [X] YES [] NO [] N/A DOOR: [X] YES [] NO [] N/A TRANS: Automatic FUEL: [X] DIESEL [] GAS ANTIFREEZE TESTED: [] YES [X] NO RATING: HRS: 16,833 DOES IT RUN? [X] YES [] NO [] UNK CAN IT BE DRIVEN? [X] YES [] NO [] UNK

PHYSICAL APPEARANCE

Table with columns: BODY, GLASS, INTERIOR, MECHANICAL and rows for various components like FRONT HEAD LIGHTS, WINDSHIELD, DASH/GUAGES, ENGINE, TRANSMISSION, etc. Includes checkboxes for condition (GD, FR, PR, N/A, UKN) and options (ENCLOSED CAB, TINTED GLASS, etc.).

COMMENTS: Leaking hydraulic pistons. All 4 tires are bad. Small dents & dings all over.

EMPLOYEE'S FULL NAME (PLEASE PRINT) DATE EMPLOYEE'S SIGNATURE By signature above I do hereby certify all information contained within this report to be true and accurate to the best of my knowledge at present.